

Material & Engineering Laboratory-Taipei

TEST REPORT

HV- 12- 01643X

REPORT NO.: HV-12-01643X

PAGE: OF 3 DATE: APRIL 09, 2012

NANOSHINE LTD.

The following merchandise was submitted and identified by the vendor as:

Product Description: Light, Leather, Plastic

Ceramic PRO Style/Item No.: Manufacturer/Vendor: Nanoshine LTD.

Country of Origin: Taiwan

We have tested the submitted sample(s) as requested and the following results were obtained:

Test Required: (According to client's test specification, please see following sheets in detail.)

Heavy Metal

Test Result:

-PLEASE SEE ATTACHED SHEETS-

Date of Receive: MARCH 19, 2012

Date of Testing: MARCH 20, 2012 ~ MARCH 30, 2012

> Signed for and on behalf of SGS Taiwan Ltd.

Carlos Kao Asst. Manager



Material & Engineering Laboratory-Taipei

TEST REPORT

REPORT NO. : HV-12-01643X PAGE : 2 OF 3

DATE: APRIL 09, 2012

Heavy Metal

Lab Environmental Conditions:

Ambient temperature : $23\pm2^{\circ}$ C Relative humidity : $50\pm5\%$ RH

Test Result:

Test Item(s)	Unit	Method	MDL	Result
				No.1
ASTM F963-08 (4.3.5)		With reference to ASTM F963-08		
Heavy metal content		(4.3.5) requirement.		
Lead (Pb)	mg/kg	With reference to	2	n.d.
		CPSC-CH-E1003-09.1 method.		
Soluble Antimony (Sb)	mg/kg	With reference to ASTM F963-08. Analysis was performed by ICP-AES.	5	n.d.
Soluble Arsenic (As)	mg/kg		2.5	n.d.
Soluble Barium (Ba)	mg/kg		10	n.d.
Soluble Cadmium (Cd)	mg/kg		5	n.d.
Soluble Chromium (Cr)	mg/kg		5	n.d.
Soluble Lead (Pb)	mg/kg		5	n.d.
Soluble Mercury (Hg)	mg/kg		5	n.d.
Soluble Selenium (Se)	mg/kg		5	n.d.

Note:

- 1. mg/kg = ppm; 0.1wt% = 1000ppm
- 2. n.d. = Not Detected
- 3. MDL = Method Detection Limit
- 4. Drying condition of CPSIA : Drying in an oven at 105°C after 30 minutes.

The content of this PDF file is accordance with the original issued reports for reference only. This Test Report cannot be reproduced, except in full, without prior written permission of the Company.此 PDF 電子檔內容係根據原簽發之紙本報告製作,僅供參考用。本報告未經本公司書面同意,不可部份複製。

SGS Taiwan Ltd.



Material & Engineering Laboratory-Taipei

TEST REPORT

REPORT NO. : HV-12-01643X PAGE : 3 OF 3

DATE: APRIL 09, 2012

<u>Test Photo</u>:



- The End of Test Report -

The content of this PDF file is accordance with the original issued reports for reference only. This Test Report cannot be reproduced, except in full, without prior written permission of the Company.此 PDF 電子檔內容係根據原簽發之紙本報告製作,僅供參考用。本報告未經本公司書面同意,不可部份複製。

| No.35, Wu Chyuan Road, New Taipei Industrial Park, Wu Ku District, New Taipei City, Taiwan/新北市五股區(新北產業園區)五權路 35 號

SGS Taiwan Ltd.